



Items Required for Installation

Potentiometer



Treble Bleed Circuit



Installation Wiring Diagram

